



14240 Eleven Mile Road. Warren, Michigan 48089. (586)776-2121 Fax (586)776-3529
 335 Cameron Circle, Ste 2, Myrtle Beach, South Carolina 29579.(843)236-1419 Fax(843)236-1428

REPAIR REPORT

Customer: DEMO

Item: AC OUTPUT MODULE

Repair #: **1119AIC**

Manufacturer: ALLEN BRADLEY

PO#: 393304591

Model #: 17710AD

Ref #1: 304591

Serial #: SD0OH1RW

Ref #2:

CC / Dept: COST1

Machine ID: 0

Warranty Repair:

Repair Description

Problem Found DISCRETE COMPONENT FAILURE

Comments Fuse was blown

Work Completed Replaced fuse. System tested all outputs under max load conditions for several day. Cleaned circuit board and edge connectors.

Parts Replaced 1-10 250V 314 Fuse

Other Info

Test Process: System Test Bench Test Component and Static Test Calibrated

Technician: 02

Date: 6/15/2006